


CORNER RECORD

DPD-3011 (Rev. 9/97) CT# 7541-4548-0

Document Number 1N26-16-18City of _____ County of Monro, CaliforniaBrief Legal Description RIGHT-OF-WAY MONUMENTS IN SECTION 16, T.1 N., R.26 E., M.D.M.**CORNER TYPE**

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey 4-29-03

COORDINATES (Optional)

N. 661725.300
 E. 2122141.806
 Zone 3 NAD27 NAD83 ☒
 NAD83 Epoch 1986
 Elevation _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric ☒ Imperial

Corner - Left as found Found and tagged Established ☒ Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SET MONUMENTS AS NOTED BELOW AT RIGHT-OF-WAY ANGLE POINTS
LABLED; 1238+60.897 33.875 LT., 1240+09.026 86.268 LT., AND
1240+71.802 82.233 LT., AS SHOWN ON RECORD OF SURVEY
34-76, RECORDED IN RS BOOK 3, PAGES 9A-U, IN THE OFFICE
OF THE MONRO COUNTY RECORDER.

A description of the physical condition of the monument as found and as set or reset: SET 20MM x 760MM

REBAR WITH "CALTRANS" ALUMINUM CAP FLUSH WITH GROUND,
STAMPED; RW A.P.


SET METAL WITNESS POST 1.0M TOWARD MNO-395

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on APRIL 30, 2003Signed Karl A. Riesen P.L.S. or R.C.E. Number 7285

For the State of California
 Department of Transportation

**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received MAY, 2003 and examinedand filed 12.08.04Signed R. Boardman P.L.S. or R.C.E. Number 4686Title County Surveyor

County Surveyor's Comment _____

