

Bk 31 Pg 78

CORNER RECORD

APN No. _____ (Optional)

Document Number CR 3507

City of LIVERMORE

County of ALAMEDA, California

Brief Legal Description STREET MONUMENT LOCATIONS

CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☐
Rancho ☐ Other ☒
Date of Survey SEPTEMBER 16, 2008

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

In compliance with Section 8771 of the Professional Land Surveyors' Act, this corner record is being filed to ESTABLISH X / REESTABLISH _____ the position of an existing monument PRIOR X / SUBSEQUENT _____ to street or highway reconstruction. (Use this portion only when applicable.)

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: STANDARD STREET MONUMENTS ALONG LAS POSITAS ROAD, LIVERMORE, CA

LOCATED BY ESTABLISHING A REFERENCE LINE IN AN AREA NOT TO BE EFFECTED BY CONSTRUCTION

A description of the physical condition of the monument as found and as set or reset: MONUMENTS FOUND WERE STANDARD WELL MONUMENTS IN GOOD CONDITION WITH A BRASS DISC AND PUNCH MARK.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on SEPTEMBER 16, 2008

Signed [Signature] L.S. or R.C.E. Number L.S. 6627

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 2008 and examined and filed 1-25-2009

Signed [Signature] Title County Surveyor

County Surveyor's Comment _____



