

CORNER RECORD

DPD-3011 (Rev. 9/97) CT# 7541-4548-0


Document Number

10N22-34-1

City of _____

County of MONO

, California

Brief Legal Description N 1/4 CORNER, SECTION 34, T10N., R 22E., M.D.B. & M.**CORNER TYPE**Government Corner ☒Control ☐Meander ☐Property ☐Rancho ☐Other ☐

Date of Survey

4-22-04**COORDINATES (Optional) * 691**N. 742082.955E. 2082693.627Zone 3

NAD27

NAD83 ☒NAD83 Epoch 1991.35

Elevation _____

Vert. Datum: NGVD29

NAVD88

Meas. Units: Metric

☒

Imperial

Corner -Left as found ☒Found and tagged ☐Established ☐Reestablished ☐Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 63MM (2 1/2") U.S.G.L.O. BRASS CAP ON A 25MM (1") O.D.I.P.
UP 0.35M, STAMPED AS SHOWN ON REVERSE, IN GOOD CONDITION
ON STEEP E'LY FACING SIDE HILL WEST OF HIGHWAY AND
TOPAZ LAKE.

A description of the physical condition of the monument as found and as set or reset: _____


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on APRIL 26, 2004Signed Karl A. RiessenP.L.S. or R.C.E. Number 7285

For the State of California

Department of Transportation

**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received MAY, 2004 and examinedand filed 12-08-04Signed R. BOARDMANP.L.S. or R.C.E. Number 4686Title COUNTY SURVEYOR

County Surveyor's Comment _____

